

Oberstraße 3, 47829 Krefeld, Germany
Phone: +31 6 22 97 10 53 E-mail: info@restposten.eu
W: www.restposten.eu

Restposten.eu GmbH Grading Overview – Explanation

New = New

Used:

- A Grade: Used condition, tested & functional, in good condition with normal usermarks.
- B Grade: Used condition, tested & functional, can be moderately damaged or have heavy signs of usermarks.
- C Grade: Used condition, tested or not-tested (it will always be mentioned), condition of item unknown, can be damaged, incomplete or have similar issues.

Observation Codes Explanation (ObservCode) For Computer Systems & Laptops

BAT BATTERY

BATA1 broken or loose latch on battery
BATF1 battery charge duration under 30 min
BATF2 battery not charging
BATF3 swollen battery
BATM1 missing battery

CAB CABINET

CABA1 minor cosmetic blemishes on cabinet
CABA2 cracks, scratches or unremovable stains on cabinet
CABA3 faded color ok cabinet plastic
CABA4 peeling paint on cabinet
CABA5 dented metal lid
CABA6 permanent security marks on cabinet
CABA7 minor breakage on cabinet
CABA8 major breakage on cabinet
CABF1 loose laptop hinges
CABF2 broken laptop hinges
CABF3 missing or broken latch on laptop lid
CABF4 faulty fan
CABM1 missing cosmetic parts
CABM2 missing essential parts
CABM3 missing fan
CABM4 missing or unreadable number on cover



CoC: HRB 19829



VAT: DE333321225



Steuer-Nr.: 345/5870/5603

TERMS AND CONDITIONS

Our terms and conditions apply to all our products and services; they can be found on our website: www.restposten.eu and a copy is attached as PDF. Everything we sell is without warranty and AS-IS.

Oberstraße 3, 47829 Krefeld, Germany

Phone: +31 6 22 97 10 53 E-mail: info@restposten.eu

W: www.restposten.eu

HDD HARDDRIVE

HDDF1 bad sectors in hard drive

HDDF2 noisy hard drive

HDDF3 defective hard drive

HDDF4 unkown password

HDDF5 incompatible hard drive

HDDM1 missing hard drive caddy

HDDM2 missing hard drive

KEY KEYBOARD

KEYA1 worn keys

KEYF1 non-working key(s) on keyboard

KEYF2 loose key(s)

KEYF3 unuseable keyboard

KEYF4 loose keyboard

KEYM1 missing keycap(s)

LCD LAPTOP LCD

LCDA1 light scratches on LCD, not visible when turned on

LCDA2 deep scratches or unremovable stains on LCD

LCDA3 pressure marks on LCD

LCDF1 LCD low brightness

LCDF2 LCD spots of white light

LCDF3 few or scattered dead/lit pixels

LCDF4 line of dead/lit pixels on LCD

LCDF5 area of dead/lit pixels on LCD

LCDF6 LCD unbalanced RGB colors

LCDF7 unuseable LCD - dark, no image, other defects

LCDF8 broken LCD glass

LCDM1 missing stylus

NET NETWORK

NETF1 non-working wired LAN

NETF2 non-working wifi

NETF3 non-working bluetooth

NETF4 non-working WLAN



CoC: HRB 19829



VAT: DE333321225



Steuer-Nr.: 345/5870/5603

TERMS AND CONDITIONS

Our terms and conditions apply to all our products and services; they can be found on our website: www.restposten.eu and a copy is attached as PDF. Everything we sell is without warranty and AS-IS.

Oberstraße 3, 47829 Krefeld, Germany

Phone: +31 6 22 97 10 53 E-mail: info@restposten.eu

W: www.restposten.eu

OPT OPTICAL DRIVE

OPTA1 optical drive - cosmetic defects

OPTF1 optical drive tray does not eject

OPTF2 noisy optical drive

OPTF3 defective optical drive

OPTM1 missing optical drive

POI POINTING DEVICE

POIA1 touchpad - worn button(s)

POIA2 scratched or stains on touchpad

POIF1 touchpad - inaccurate movement

POIF2 touchpad - defective left button

POIF3 touchpad - defective right button

POIF4 defective touchpad

POIM1 touchpad - missing button(s)

GEN GENERIC

GENA2 - major cosmetic defects

GENF1 - non-working product - zero activity

GENF2 - non-working product - errors on startup

GENF3 - non-working product - broken

GENF4 - Unknown password on startup

GENF5 - defective ram

GENF6 - defective or damaged motherboard

GENF7 - broken LCD

GENM1 - missing ram

GENM2 - missing hard drive

GENM3 - missing processor

GENM4 - missing motherboard

GENM5 - missing power supply unit

GENM6 - missing videocard



CoC: HRB 19829



VAT: DE333321225



Steuer-Nr.: 345/5870/5603

TERMS AND CONDITIONS

Our terms and conditions apply to all our products and services; they can be found on our website: www.restposten.eu and a copy is attached as PDF. Everything we sell is without warranty and AS-IS.

Oberstraße 3, 47829 Krefeld, Germany

Phone: +31 6 22 97 10 53 E-mail: info@restposten.eu

W: www.restposten.eu

Observation Codes Explanation (ObservCode) For Smartphones & Tablets

BAT BATTERY

BATF1 low battery charge duration

BATF2 battery not charging

BATM1 missing battery

CAB CABINET

CABA1 minor cosmetic blemishes on cabinet

CABA2 major cosmetic blemishes on cabinet

CABA3 permanent security marks on cabinet

CABF1 broken or unusable physical button(s)

CABM1 missing cosmetic parts

CABM2 missing back cover or other essential part

CAM CAMERA

CAMF1 defective front camera

CAMF2 front camera - poor quality image

CAMF3 defective back camera

CAMF4 back camera - poor quality image

LCD - LCD

LCDA1 light scratches on LCD not visible when turned on

LCDA2 deep scratches or unremoveable stains on LCD

LCDA3 glass cracked but LCD fully usable

LCDF1 LCD - low brightness

LCDF2 LCD - spots of white light

LCDF3 LCD - few or scattered dead/lit pixels

LCDF4 line of dead/lit pixels on LCD

LCDF5 area of dead/lit pixels on LCD

LCDF6 LCD - unbalanced RGD colors

LCDF7 unuseable LCD - dark, no image, other defects

LCDF8 unuseable LCD - glass cracked

LCDF9 touch LCD malfunction



CoC: HRB 19829



VAT: DE333321225



Steuer-Nr.: 345/5870/5603

TERMS AND CONDITIONS

Our terms and conditions apply to all our products and services; they can be found on our website: www.restposten.eu and a copy is attached as PDF. Everything we sell is without warranty and AS-IS.

Oberstraße 3, 47829 Krefeld, Germany

Phone: +31 6 22 97 10 53 E-mail: info@restposten.eu

W: www.restposten.eu

OTH OTHER

OTHF1 unable to establish a call or poor quality

OTHF2 microphone not working or poor quality

OTHF3 vibration not working

OTHF4 flashlight not working

OTHF5 proximity sensor not working

OTHF6 accelerometer not working

OTHF7 GPS not working

OTHF8 unknown iCloud password

OTHM1 SD card required and missing

POR PORTS

PORF1 USB - no data connection

PORF2 unuseable USB port

PORF3 unuseable headset port

PORF4 unuseable SD-card reader

PORF5 unuseable SIM card reader

POW POWER SUPPLY

POWF1 power adapter - peeled cable, broken connector

POWF2 defective power supply unit / adapter

POWM1 missing power adapter / USB cable

SND SOUND

SNDF1 no sound on loudspeaker

SNDF2 poor quality sound

Voor meer informatie, vragen of opmerkingen over de observatie codes, kunt u contact met ons opnemen.

For more information, questions or comments about the observation codes, you can always contact us.



CoC: HRB 19829



VAT: DE333321225



Steuer-Nr.: 345/5870/5603

TERMS AND CONDITIONS

Our terms and conditions apply to all our products and services; they can be found on our website: www.restposten.eu and a copy is attached as PDF. Everything we sell is without warranty and AS-IS.